



CORNING ASAHI VIDEO

Brandenburg was contracted to remediate the facility and then demolish most of the operating facility leaving only a few warehouse-type structures.

OWNER

Corning Asahi Video

LOCATION

State College PA

FACILITY TYPE

Manufacturing plant

PROJECT BACKGROUND

Corning Asahi Video's State College manufacturing plant produced electronic picture tubes and other glass for televisions and monitors. The operating facility became obsolete due to changes in technology and the plant was closed in 2003. Most of the equipment was salvaged and sold to other manufacturing facilities. Brandenburg was contracted to remediate the entire facility and then demolish most of the operating facility leaving only a few empty warehouse-type structures. The work was in preparation to renovate the property for sale as prime industrial real estate.

SCOPE OF WORK

Perform utility cut-offs and re-routes

Remove asbestos containing material including floor tile, pipe insulation, and galbestos sheeting

Power wash the entire facility to remove lead contaminated residue

Separate connected buildings and provide support and protection to the buildings to be saved

Decontaminate and remove three large glass furnaces

Remove two 175' tall brick smoke stacks, three cullet silos and 33 batch silos

Remove buildings down to grade

Excavate and dispose of contaminated soil

